

## D.L.P.C. COMPLAINT INVESTIGATION FORM

US EPA RECORDS CENTER REGION 5



481468

0310090001

Cook

County

Arlington Heights Municipal

FOS File

Complaint #: C89-148N

Date Received 2/6/89 By JM By Phone ☒ In Person ☐ By Mail ☐

Complainant John Tomaras (MSD) Respondent Arlington Heights

Address

Address

Arlington Heights, IL 60005

Telephone 312/299-3922

Telephone

Directions to Source Contact John Tomaras to accompany on visit

Complaint Details Leachate seeping into an Illinois Bell Telephone (IBT) vault from the old landfill.

(? - Monitoring well info on the site?)

\*\*\*\*\*

## INVESTIGATION FINDINGS

Date 02-24-89 Time By G. Bruni

Interviewed Joe Lasky and Gerry Voff Weather O'F, SUNNY Photos (2)  
OF Illinois Bell Telephone

Remarks:

RECEIVED

MAR 14 1989

IEPA-DLPC

\*\*\*\*\*

cc:

Updated Complaint Log  
with investigation result:



STATE OF ILLINOIS  
ENVIRONMENTAL PROTECTION AGENCY  
INSPECTION REPORT

USEPA Number: N/A IEPA Number: 0310090001

Facility Name: Arlington Heights Municipal Landfill

Street: Rt. 68 & Kennicott Ave.

City: ARLINGTON HEIGHTS Telephone: 312/253-2340

County: COOK State: IL Zip Code: 60005

Type of Facility: Notified as: N/A Regulated as: N/A

LDF?    HPV?    90 Day Follow-up required? Yes:    No:   

Region: MIDWEST Date of Inspection: 02-24-89 From: 9:00am to: 10:30am

Weather (LDF Only):   

Type of Inspection

ISS:    Sampling:    Citizen Complaint: ✓ Closed:    Other:   

Record Review:    Follow-up to Inspection of:    Withdrawal:   

Non Regulated Status

SOG:    Claimed Nonhandler:    Other (Specify in Narrative):   

Notification date,   , from (initial) or (subsequent) Notif.

Part A

Initial Part A date:    Amended:   

Part A Withdrawal requested:    Approved by (US)(IL)EPA:   

Part B Permit Application

Part B Permit called by (US)(IL)EPA on:    Permit Due:   

Part B Permit Submitted:    Draft Permit Issued:   

Enforcement

Has the firm been referred to: USEPA?    IAG?    County SA?   

Date(s) of initial referral:   

USEPA CACO:    CAFO:    ALJ Decision:   

Referral to DOJ by USEPA:    Federal Court Order Issued:   

PCB Order Issued:    State Court Order Issued:   

TSD Facility Activity Summary

Activity By Process Code	On Pt A?	Activity Conducted Prior to 1980?	Was Activity Ever Done?	Closed	Being Done at Time of Insp?	Exempt per 35 IAC, Sec.	On Annual Report

RECEIVED

MAR 14 1989

IEPA-DLPC

CONFIDENTIAL

Complaint Investigation  
(C89-148N)

On February 24, 1989 Tom Enno and I met Joe Lasky, Gerry Voll of Illinois Bell, and John Tomaras of the Metropolitan Sanitary District of Greater Chicago.

Allen J. Sander Director of Public Works for the Village of Arlington Heights was notified by myself, that the Agency will be conducting a complaint investigation (89-148N) at the Arlington Heights Municipal Landfill on February 24, 1989. Mr. Sander indicated a representative of the Village would be present. During the investigation we did not meet a Arlington Heights representative.

The Village of Arlington Heights is the owner/operator of the Arlington Heights Municipal Landfill. The landfill accepted municipal refuse from about 1964 until about 1974. During a December 16, 1975 Agency inspection, approximately 100-55 gallon drums were observed at the southwest corner of the landfill near the large water storage tank. Most of the drums appeared empty. Labels were found on the drums (AERO Shell Fluid #4, and Dupont Flour Carbon TF & TE solvent a light Cy oil). Approximately 40 drums filled with various unknown liquids were transported to Lake Landfill Inc. on February 9, 1976 for disposal.

On two other occasions 55 gallon drums were observed by the Agency. Drums were found in a pond at the southwest corner of the landfill and being buried. Harza Environmental Services, Inc. was retained by the Village to develop a closure and post closure care plan. The plan was submitted in September 1988.

During the complaint investigation (89-148N) four samples were taken from Illinois Bell Telephone vault #3. Vault #3 is located along the east side of the Landfill. Vault #3 is about 15 feet deep. It contained approximately 6 feet of liquid. The samples were clear and odorless. Samples will be tested for the following parameters:

- \* Total Metals
- \* Organic's
- \* VOC's

Liquid found in vault #3 does not appear to be a leachate from a landfill. A conclusion will not be made, until sample results are received.

1532P

cc: Division  
Maywood Region

RECEIVED

MAR 14 1989

IEPA-DLPC

NICHOLAS BLVD.

⑦

⑥ MANHOLE

⑤

LAND FILL

OWNED BY THE  
VILLAGE OF  
ARLINGTON HEIGHTS

③01





-001  
25' DIA.

VAULT #3  
MANHOLE

③

MANHOLE - ④

④



⑩02 MAR 14 1989  
IEPA-DLPC